

76C TEST SET
DESCRIPTION AND MAINTENANCE
AND ESTABLISHING TALK AND/OR CALLING CIRCUIT

1. GENERAL

1.001 This addendum supplements Section 634-200-501, Issue 4. Place this pink sheet ahead of Page 1 of the Section.

1.002 This addendum is issued to show the 76C test set as rated manufacture discontinued (Mfr Disc.).

1.003 The recommended replacement test set is the 146A test set (see Section 634-200-504).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.