

PLANT SERVICE CENTER REFERRALS
TO DDD SERVICE BUREAUS

1. GENERAL

1.01 This Appendix is issued to provide a telephone number reference list of DDD Service Bureaus (DDSB) for use by Plant Service Centers (PSC).

1.02 PSC's shall refer trouble conditions in the toll switching plant to the

DDSB serving the Numbering Plan Area (NPA) in which the PSC is located. Included are such reports referred to in F21.101.13, Paragraphs 4.13 and 4.14, and V68.102, Paragraph 2.07.

1.03 The following list provides telephone numbers of DDSB's and their serving NPA's:

<u>DDSB</u>	<u>NPA</u>	<u>Telephone</u>
Dallas, Texas	214	214-821-3500
St. Louis, Missouri	314 + Part of 618	314-247-4241
Wichita, Kansas	316	316-363-5766
Oklahoma City, Oklahoma	405	405-236-7851
Springfield, Missouri	417	417-866-1011
Little Rock, Arkansas	501	501-376-9766
San Antonio, Texas	512	512-222-3503
Houston, Texas	713	713-224-7455
Lubbock, Texas	806 + 915	806-763-9421
Kansas City, Missouri	816	816-221-7676
Ft. Worth, Texas	817	817-336-6587
Salina, Kansas	913	913-825-0261
Tulsa, Oklahoma	918	918-582-5264