

PLUG-IN EQUIPMENT

DIGITS 1 - 10	MANUFACTURING DRAWING	LISTS OR GROUPS
RC00A623AA	KNTX	33820022
RC00L422AA	LEAR	RC-7118-L1
RC00L722AA	LEAR	RCD-7175-L1
RC00MA04AA	PLSE	1691-5
RC00MA14AA	PLSE	1691-4L1
RC00MB04AA	PLSE	1691-6L1
RC00MC04AA	PLSE	1691-6L2
RC00MD04AA	PLSE	1691-8
RC00N116AA	RIXN	RC13-R00
RC00N116AB	LNTE	RC5023-L3
RC00N126AA	RIXN	RC12-R00
RC00N126AB	LNTE	RC5023-L2
RC00N226AA	RIXN	RC11-R00
RC00N226AB	LNTE	RC5023-L1
RC00P122AA	PRTR	61976
RC00R245AA	TSCM	SSP-440
RC00R255AA	TSCM	SSP-440-01
RC00T704AA	TSLS	814422
RC00T734AA	TSLS	814423
RC00T804AA	TSLS	814421
>RC00W111AA	WSCM	730200I01
>RC00W121AA	WSCM	730100I01
>RC00W221AA	WSCM	073000I01
>RC00Z311AA	WSCM	669400I01

HARD WIRED EQUIPMENT

DIGITS 5 6 7 8	CIRCUIT DRAWING	FIGURES	OPTIONS
K 2 3	KNTX CL		-
5			85200005
6			85200001 OR 27240
> 9			OR 27740 FOR 2 WIRE
			85200001 OR 27240
			OR 27740 FOR 4 WIRE
U 0 1	LRUS CL		-
1			24008 OR 24016
2			24108 OR 24116