

PLUG-IN EQUIPMENT

DIGITS MANUFACTURING
1 - 10 DRAWING LISTS OR GROUPS

L3MU10AAAA	J68829H-91	1
L3MU10BAAA	J68829H-91	1, SA
L3MU20AAAA	J68829H-91	3
L3MU20BAAA	J68829H-91	3, SA
L3MU30AAAA	J68829H-91	2
L3MU40ABAA	J68829H-91	4
L3MU40BBAA	J68829H-91	4, SA
L3MU50ABAA	J68829H-91	5
L3MU50BBAA	J68829H-91	5, SA
L3MU60ABAA	J68829H-91	6
L3MU60BBAA	J68829H-91	6, SA
L3MU70ABAA	J68829H-91	7
L3MU70BBAA	J68829H-91	7, SA