

URGENT INSTRUCTION SUPPLEMENT
PROTECTING AND REPAIRING WIRING
PROTECTING SKINNERS, APPARATUS TERMINALS AND LIVE LEADS

1. GENERAL

1.1 The purpose of this UIS is to remove the misleading requirement information associated with Paragraph 3.6111, to change KS-7851 Varnish Impregnated Sleeving to Fiberglass-PVC Coated Sleeving and to remove the P-365046, P-368775 and P-40C391 Wax Impregnated Sleeving.

2. INSTRUCTIONS

2.1 Change Paragraph 2.2 from -KS-7851 Varnish Impregnated Sleeving from - KS-7851 Varnish Impregnated Sleeving

RM-581228 Black No. 7 (.148" ID) 3' Lg.
RM-621804 Black No. 8 (.133" ID) 3' Lg.
RM-581229 Black No. 9 (.118" ID) 3' Lg.
RM-628431 Black No. 10 (.107" ID) 3' Lg.
RM-628413 Black No. 13 (.076" ID) 3' Lg.
RM-628436 Black No. 14 (.068" ID) 1-1/4" Lg. (500 Pcs/Bx)
RM-681514 Black No. 14 (.068" ID) 2-3/4" Lg. (100 Pcs/Bx)
RM-628437 Black No. 18 (.044" ID) 3' Lg.
RM-628411 Red No. 8 (.133" ID) 3' Lg.
RM-581590 Yellow No. 0 (.328" ID) 3' Lg.
RM-581510 Yellow No. 9 (.118" ID) 3' Lg.
RM-581592 Yellow No. 11 (.095" ID) 3' Lg.

To - KS-7851 L-3 Fiberglass-PVC Coated Sleeving

No. 7 Black (.148" ID) 3' Lg.
No. 8 Black (.133" ID) 3' Lg.
No. 9 Black (.118" ID) 3' Lg.
No. 10 Black (.107" ID) 3' Lg.
No. 13 Black (.076" ID) 3' Lg.
No. 14 Black (.068" ID) 1-1/4" Lg. (500 Pcs/Bx)
No. 14 Black (.068" ID) 2-3/4" Lg. (100 Pcs/Bx)
No. 18 Black (.044" ID) 3' Lg.
No. 8 Red (.133" ID) 3' Lg.
No. 0 Yellow (.328" ID) 3' Lg.
No. 9 Yellow (.118" ID) 3' Lg.
No. 11 Yellow (.095" ID) 3' Lg.

NOTICE - NOT FOR USE OR DISCLOSURE OUTSIDE THE BELL
SYSTEM EXCEPT UNDER WRITTEN AGREEMENT

Printed in U.S.A.

Remove - Wax Impregnated Cotton Sleeve

P-365046 Black (.040" ID) 1-1/2" Lg. (500 Pcs/Bx)

P-368775 Black (.070" ID) 1-1/2" Lg. (500 Pcs/Bx)

P-40C391 Black (.040" ID) 2-3/4" Lg. (500 Pcs/Bx)

2.2 Change Paragraphs 3.21, 3.35, 3.52, 3.54, 3.61, 3.612 and Figures 3, 4, and 6 which all reference "KS-7851 Varnish Impregnated Sleeve to read: KS-7851 L-3 Fiberglass-PVC Coated Sleeve.

2.3 Change Figure 2 to remove reference to RM-628431, RM-581229, RM-621804, and RM-581228.

2.4 Change Paragraph 3.55 to remove reference to RM-628436.

2.5 Change Paragraph 3.611 to remove the requirement bracket line.

2.6 Change Figure 5 as follows: Remove RM-628413 Sleeving and add No. 13 Black Sleeving.

2.7 Change Paragraph 3.72 as follows:

Remove: Leads for Soldered Connections

P-365046 (1-1/2" Lg.) for No. 22 gauge or smaller leads

P-368775 (1-1/2" Lg.) for No. 20 gauge or larger leads

Leads for Solderless Wrapped Connections

P-40C391 (2-3/4" Lg.) for 22 gauge and smaller leads.

Add: Leads for Soldered Connections

KS-7841 L-3 No. 14 (1-1/4" Lg.) for 20 gauge and smaller leads,

Leads for Solderless Wrapped Connections

KS-7851 L-3 No. 14 (2-3/4" Lg.) for 20 gauge and smaller leads

2.8 Change Paragraph 3.723 as follows:

Remove: Apply a light coat of Orange Shellac Varnish (RM-646482) to the tape in all cases.

Replace with: Apply a light coat of R-3455 White Shellac to the tape in all cases.

Engineering Planning Manager
(Installation)