

MAIN FRAME PROTECTION "B" TYPE FRAMES

1. GENERAL

1.001 This addendum supplements Section A302.001, Issue 8.

1.002 This addendum is issued to revise Table 1 to identify the No. 29B and 30 protector blocks.

The following change applies to Part 1 of the section:

(a) Table 1 — Footnote marked with triple asterisk (***) revised.

*** Where the MDF protector mountings are connected to drainage coil assemblies, substitute No. 29B (.006 stamped on side) for No. 29 (unmarked) protector blocks; substitute No. 30 (blue color code on porcelain) for No. 27 (unmarked) protector blocks.

Note: Where the No. 377H transformer is used, use the No. 15 and 9 dummy protector blocks, respectively.