


CODED TOOLS
 NOS. 396A TO 406B


TOOL, 396A



Rack locator.

For use on panel selector elevator apparatus.


TOOL, 397A



Anvil guide plates.

For use in repairing A and B type sequence switch cams.


TOOL, 398A



Perforating punch.

For use in repairing A and B type sequence switch cams.


TOOL, 398B



Rivet heading punch.

For use in repairing A and B type sequence switch cams.


TOOL, 400A



Commutator brush spacer.

For use on 10 and 14 type commutator brushes.

SECTION A706.026



Oil gun. Supplied with one straight nozzle. The P-249511 Nozzle, which is curved, is available separately and not supplied with the tool except when so specified in the order. Designed to discharge oil in definite limited quantities. Furnished with a wooden carrying case per Dwg. A146059.

For general use.


TOOL, 402A Manufacture Discontinued. Replaced by the No. 402C tool.

TOOL, 402B Manufacture Discontinued. Replaced by the No. 402D tool.

TOOL, 402C Manufacture Discontinued. Replaced by the No. 402E tool.

TOOL, 402D Manufacture Discontinued. Replaced by the No. 517B tool.

TOOL, 402E




Bank contact cleaner.

Replaces the No. 402C tool.

For use in cleaning and treating the contacts of 200 point banks of 197 type switches.


TOOL, 403A



5/32" and 3/16" Hex. double end socket wrench. This tool forms a part of the No. 72 tool.

For general use.


TOOL, 404A



Rack locator.

For use on panel tandem and cordless "B" link elevator apparatus

TOOL, 405A



Bumper.

Replaces bumper, R-80215.

For use on plunger type line switches.

TOOL, 406A Manufacture Discontinued. Replaced by No. 406B tool.

TOOL, 406B Manufacture Discontinued.