


CODED TOOLS

NOS. 530A to 542A

TOOL, 530A Manufacture Discontinued.
 Replaced by the No. 560A tool.

TOOL, 532A Manufacture Discontinued.
 Replaced by the No. 532B tool.

TOOL, 532B




Adjuster.

Replaces the No. 532A tool

For use on 300-, 304-, 314-, 324- and similar type switches and 245-, 254-, 263- and 264-type relays.


TOOL, 533A



Bearing lug adjuster.

For use on 300-, 304-, 314-, 324- and similar type switches

- TOOL, 534A
- TOOL, 534B
- TOOL, 534C
- TOOL, 534D
- TOOL, 534E
- TOOL, 534F
- TOOL, 534G
- TOOL, 534H




Code	Slot Width	Dim. "A"
534A	.025"	1"
534B	.031"	1"
534C	.035"	1"
534D	.043"	1"
534E	.018"	1"
534F	.025"	1-11/16"
534G	.031"	1-11/16"
534H	.043"	1-11/16"

Spring adjusters.

Nos. 534A, 534B, 534C, 534D and 534E tools are for use on 300-, 304-, 314-, 324- and similar type switches.
 No. 534D tool is also for use on 266-type relays.

Nos. 534F, 534G and 534H tools are for use on AF-, AG- and AJ-type relays.

- TOOL, 535A
- TOOL, 535B



Code	Slot Width
535A	.018"
535B	.020"

Spring adjusters.

No. 535B tool replaces the D-178348 tool.


No. 535A tool is for use on 300- and similar type switches, 216-type switches and 245-, 254-, 263- and 264-type relays.

No. 535B tool is for use on KS-13835 readers.

SECTION A706.038

TOOL, 536A Manufacture Discontinued.
Replaced by the No. 536B tool

TOOL, 536B




Selecting bar holder.

Replaces the No. 532A tool.

For use on 300-, 304-, 314-, 324- and similar type switches.


TOOL, 537A



Strap wire tool.

For use on 300-, 304-, 314-, 324- and similar type switches and 245-, 254-, 263- and 264-type relays.


TOOL, 538A



9/32" hex. offset socket wrench.

For use on 300- and similar type switches.


TOOL, 539A



1/4" hex. open double-end wrench.

For use on 300- and similar type switches and KS-8543 and KS-8564 timers.

TOOL, 541A



1/4" 12-point double-end box wrench.

For general use.

TOOL, 542A Manufacture Discontinued.
Replaced by the No. 558A tool.