

FIG. 2
CLEARANCE FOR CARD HOLDER
WHEN NOT PROVIDED ON ALUMINUM BACKPLATE
(TOP VIEW)




FIG. 1
HOLE IN LOWER HOUSING
(BOTTOM VIEW)

COIN COLLECTORS
HOLE IN LOWER
HOUSING & CLEARANCE
FOR CARD HOLDER
IN BACKPLATE

APPLS			
CH.			
DR.		ENG.	

BELL TELEPHONE
LABORATORIES, INC.
NEW YORK

LA-

NO. OF SHEETS PER SET SEE SHEET 1

B-930657