

Printed in U. S. A.

BELL SYSTEM PRACTICES WR-B502.531
Private Branch Exchange WR-B502.535
Installation and Maintenance WR-B502.541
Issue 3, 1-11-44
AT&TCo

SUBSTITUTES FOR SHELLAC

1. GENERAL

1.01 This sheet covers wartime substitutions for shellac (shellac varnish) now used for various purposes in private branch exchanges and supplements the sections listed herein.

1.02 This WR sheet is reissued to substitute KS-7435 Thinner for Solvent Naphtha as a solvent for RK302 Varnish. Previous issues of this WR sheet were not distributed.

2. MATERIAL SUBSTITUTION

2.01 Substitute RK302 Varnish (E.I. DuPont de Nemours) for shellac now specified in the List of Materials in the following sections.

Section B502.531
B502.535
B502.541

2.02 Add to the List of Materials in the above mentioned sections the following solvent - KS-7435 Thinner (Solvent for RK302 Varnish).

WR-B502.531
WR-B502.535
WR-B502.541
Page 1
1 Page

SUBSTITUTES FOR SHELLAC