

**BELL SYSTEM PRACTICES**  
**Station Installation and Maintenance**

**ADDENDUM C32.559**  
**Issue 1, April, 1956**  
**AT&T Co Standard**

## **TELEPHONE SETS**

### **554, 556, AND 558 TYPES**

### **DESCRIPTION AND USE**

#### **1. GENERAL**

1.01 This addendum supplements Section C32.559, Issue 1. It is issued to add information on C4A ringers used in these telephone sets.

#### **2. DESCRIPTION**

2.02 Change to read: These sets are shown with the housing removed in Figs. 3, 4, and 5. All components of these sets, except the early model C4A ringers, are interchangeable with the components of the 500-type telephone sets. The frames on all C4A ringers manufactured after January 15, 1955 have been changed in design so that they will not interfere with the free movement of the volume-adjusting arm as did the earlier model.