

REPAIRING CABLE - AERIAL

TORCH METHOD OF REPAIRING SHEATH

NOTES CONCERNING THIS ADDENDUM

This Addendum supplements G50.440.1 and contains information relative to the use of the acetylene torch in repairing sheath defects.

The cross-reference "See Addendum" should be written at Paragraph 1.02 of G50.440.1.

1. GENERAL

- 1.02 Note: Repair operations with a torch may also be done while working from a pole.