

Distribution Code

CHECKING LIST
 AND INDEX
 CONSTRUCTION AND
 MAINTENANCE FORCES

- A - Dist. Engs., Const. Supts.,
 Supv. Engs., Supv. Const.
 Fore.
- B - Construction Foremen
- C - Splicing and Shop Foremen,
 Chief Cable Testers
- D - Foremen of Cablemen,
 Subway Inspection Group
- E - Splicers
- F - A Cutters

*New or revised since previous
 issue of this section.

%Change in distribution.

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
	<u>Underground Cable</u>		
Checking List and Index	*G55.000.1	J	AFCDEF
Precautions	*G55.090.1 Add.	A	ABCDE-
	*G55.090.1	1	
Selection of Ducts in Measuring for Cable	G55.105.1	1	ABCD--
Placing - Rodding and Cleaning Ducts	*G55.106.1 Add.	A	AB-D--
	G55.106.1-S	A	

<u>Subject</u>	<u>Section</u>	<u>Issue</u>	
<u>Underground Cable (Continued)</u>			
Placing - Setting Up Reel and Apparatus	G55. 110. 1-S Add. G55. 110. 1-S	A A	ABCD--
Attaching Pulling Line	G55. 110. 2 Add. G55. 110. 2	C 3	ABCD--
Placing - Feeding and Pulling Cable	*G55. 110. 3	3	AB-D--
Placing - Sealing Ends	G55. 110. 4 Add. G55. 110. 4	A 3	ABCDE-
Placing - Tying, Tempo- rary Bonding and Tagging Duct Splices	G55. 110. 5	2	ABCD--
Pulling Cable into Subsidiary Ducts	G55. 130. 1 Add. G55. 130. 1	A 1	ABC---
Pulling Cable Into Central Offices	G55. 140	1	A-CD--
C. O. Cable Vaults - List of Unistrut Material	G55. 145. 1 Add. G55. 145. 1	A 1	A-C---
C. O. Cable Vaults - Con- struction of Unistrut Frame	G55. 145. 2 Add. G55. 145. 2	A 1	A-----
Sealing Ducts - Con- ditions Requiring Seals	G55. 150. 1	1	ABCDE-
Sealing Ducts - Solid Rub- ber Conduit Plugs	G55. 150. 3	1	ABCDE-
Sealing Ducts - Split Rub- ber Conduit Plugs	G55. 150. 5	1	ABCDE-
Sealing Ducts - Wooden Conduit Plugs	G55. 150. 7	1	ABCDE-
Sealing Ducts - Calking Materials	G55. 150. 9	1	ABCDE-

Prevention of Cable Creepage in Underground Conduit	G55.152.1	1	A-CD--
Repairing - Alpeth Sheath Cable	G55.442.1	1	A-C-E-
Removing Underground Cable	G55.505 Add. G55.505	1 3	ABCD--
General Rules - Setting Up Cable	G55.601.1 Add. G55.601.1	C 1	A-C-E-
Setting Up Lead Sheath Cable - One Man in Hole	G55.603.1	1	A-C-E-
Setting Up Lead Sheath Cable - Two Men in Hole	G55.603.2	1	A-C-E-
Setting Up Lead Sheath Cable - Cable Bender	G55.603.3	1	A-C-E-
Setting Up Cable - Pull Through Manholes	G55.606.1	1	A-CDE-
Cable Arrangement in Manholes	G55.607.1 Add. G55.607.1	B 1	A-CDE-
Stub Cable Arrangement in Manholes	G55.607.2	1	A-C-E-
Bonding - Lead Sheath Cables	G55.610.1 Add. G55.610.1	A 1	A-C-E-
Bonding Alpeth Sheath Cables	G55.610.3	1	A-C-E-
Arrangement of Splices in Central Offices	G55.620.1 Add. G55.620.1	A 1	A-C-E-
Central Office Cutovers	G55.625.1	1	A-C-E-