

TERMINALS

REPAIRING BROKEN BINDING POSTS

IN NO. 14 TYPE CABLE TERMINALS

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G61, 408, 1 and is being issued to correct typographical errors and to bring material references in agreement with Catalogue of Supplies.

"See Addendum" should be marked in G61, 408, 1 to indicate the following:

- Paragraph 4.01 (3) - correct washer number to read P-207213
- Paragraph 4.01 (4) - change nut number to read P-139469
- Paragraph 4.01 (5) - correct washer number to read P-207213
- Paragraph 4.01 (10) - change washer number in sketch to read P-207213
- Paragraph 4.01 (10) - change nut number in sketch to read P-139469
- Paragraph 4.01 (13) - change washer number to read P-247394