


NOTES:

OS OPTION	FEATURE OR OPTION	SD OPTION	SD
Z	FOR OFFICES HAVING SIX OR LESS TRUNK BLOCK CONNECTORS.	Z	68395-01
Y	FOR OFFICES HAVING SEVEN TO EIGHTEEN TRUNK BLOCK CONNECTORS.	Y,Z	68395-01
X	FOR OFFICES HAVING NINETEEN TO THIRTY TRUNK BLOCK CONNECTORS.	X,Y	68395-01


2. CONTACT ASSIGNMENTS OF M-LEADS ON DCI RELAYS.

LEAD (MARKER NO.)	CONTACT NUMBER	
	EVEN DCI RELAYS	ODD DCI RELAYS
M0	10	15
M1	11	16
M2	12	17
M3	13	18
M4	14	19
M5	20	25
M6	21	26
M7	22	27
M8	23	28
M9	24	29

SEQUENCE CHART



DECODER (FOR COMBINED TRAIN OPERATION)



MARKER CONNECTOR-COMBINED TRAIN

- DECODER CKT. SD-68340-01, ISS. 8
- DECODER CONNECTOR CKT. SD-68339-01, ISS. 6
- MARKER CKT. SD-68388-01, ISS. 8
- \* MARKER CONNECTOR CKT. SD-68395-01, ISS. 4
- MISC. CKT. TROUBLE RECORDER FRAME SD-68392-01, ISS. 5

MARKER CONNECTOR  
COMBINED TRAIN OPERATION

OS 188-2

2 SHEETS, SHEET 1

NO. 4A OR 4M TOLL

ORDER AS BSP ITEM MP-11651

BELL TELEPHONE LABORATORIES, INC.  
PRINTED IN U. S. A.

ISSUE	1	2	3	4	5	6	7	8	9	10
DATE	8-16-57	11-9-53								

2 SHEETS, SHEET 1

MP-11651

ISSUE	1	2	3	4	5
DATE	6-9-57	11-15-57			

