

DECODER
**OVERALL OPERATIONS FOR A CALL
 COMPLETED BY 3-DIGIT TRANSLATION**

SC 113-1


H J K
 NO. 4A OR 4M TOLL

ISSUE	1	2	3	4
DATE	9-25-51	10-29-51		

2 SHEETS, SHEET 1

MP-11686

ISSUE	1	2	3	4
DATE	9-25-51	10-29-51		



- NOTES:
- A. IF 3D CARD DROPS WITH CA4/5/6 INSTRUCTIONS, SEE SC 114-1
 - B. IF 3D CARD DROPS WITH NCA & CC INSTRUCTIONS, SEE SC 117-1
 - C. IF 3D CARD DROPS WITH NCA & CR INSTRUCTIONS, SEE SC 118-1 OR SC121-1
 - D. IF 3D CARD DROPS WITH NCA & RR INSTRUCTIONS, SEE SC 119-1
2. THESE RELAYS RELEASE HERE IF OPERATED BY SENDER OR DECODER CONN.
- 3.

SC OPTION	FEATURE OR OPTION	SD OPTION	SD
A	PLUG IN THE JACK AT TROUBLE RECORDER FRAME ALLOWS SEIZURE OF THE EMERGENCY TRANSLATOR	NONE	
B	DECODER NOT PLUGGED BUSY AND THE EMERGENCY TRANSLATOR HAS NOT BEEN SUBSTITUTED	NONE	
C	SEPARATE TRAIN OFFICE	FIG. A	
D	COMBINED TRAIN OFFICE	FIG. B	68340-01
E	THESE RELAYS RELEASE UNLESS GROUNDED BY THE SENDER OR DECODER CONNECTOR	NONE	
F	FOR OFFICES HAVING MORE THAN 6 TRUNK BLOCK CONNECTORS	X & Y	68395-01
G	F. T. BOXES 1-8 PAIRED	FIG. C	
H	F. T. BOXES 1-16 PAIRED	FIG. D	68340-01
J	SEPARATE TRAIN COMBINED OPERATION OFFICE	FIG. E	68340-01

- INCOMING SENDER M.F. 4M SD-68424-01, ISS. 4
- INCOMING SENDER D.P. 4M SD-68423-01, ISS. 2
- CARD TRANSLATOR CKT. SD-68342-01, ISS. 6
- * DECODER CKT. SD-68340-01, ISS. 8
- DECODER CONNECTOR CKT. SD-68339-01, ISS. 4
- INCOMING SENDER CKT. D.P. 4A SD-68221-01, ISS. 14
- INCOMING SENDER CKT. M.F. 4A SD-68222-01, ISS. 16
- MARKER CKT. SD-68368-01, ISS. 7
- MARKER CONNECTOR CKT. SD-68395-01, ISS. 5
- TRANSLATOR CONNECTOR CKT. SD-68341-01, ISS. 6
- MISC. CKT. TROUBLE RECORDER SD-68392-01, ISS. 5