

**BELL SYSTEM PRACTICES**  
Teletypewriter and Data Stations

**SECTION P31.151**  
Issue 3, February, 1960  
AT&TCo Standard

## **FUSES FOR TELETYPEWRITER APPARATUS**

### **1. GENERAL**

1.01 Fuses (that is, regular quick-blowing fuses without time-delay characteristics) are no longer generally recommended for teletypewriter apparatus. Teletypewriter apparatus should preferably be equipped with **time-delay** (also called time-lag) fuses. These time-delay fuses can be Fusetrons (manufactured by the Bussmann Co.), or Slo-Blo fuses (manufactured by the Littelfuse Co.). For proper Fusetron or Slo-Blo fuse ratings see P31.152. See P31.101 for fusing of rectifiers.

**P31.151**

Page 1  
1 Page

**FUSES FOR TELETYPEWRITER  
APPARATUS**