

American Telephone and Telegraph Company

BELL SYSTEM PRACTICES  
Teletypewriter and Manual  
Telegraph Station and P.B.X.  
Installation and Maintenance

ADDENDUM P31.318  
Issue A, 1-11-43  
Long Lines Department  
Dist. Class. 608.2AC

INSTALLATION OF RADIO INDUCTION

SUPPRESSORS ON THE 128B2

TELETYPEWRITER SUBSCRIBER SET

1. GENERAL

1.01 This addendum supplements Section P31.318, Issue 3, to indicate the following corrections which should be made pending a revision of the section.

Paragraph 2.03 (2): Change "right-hand" to "left-hand."

Paragraph 2.03 (4): Change "left-hand" to "right-hand."

ADDENDUM  
P31.318  
Page 1  
1 Page

RADIO SUPPRESSORS  
128B2 SET