



- NOTES:
1. THE K5-14229, L2 REL. MAY BE OBTAINED BY MODIFYING A WARD LEONARD K42219 RELAY. THE MODIFICATION CONSISTS OF DISCARDING THE METAL HOUSING AND MOUNTING THE RELAY ON A BRACKET PER FIG. 4, THE BRACKET TO BE PROVIDED LOCALLY.
 2. THE K5-14230, L2 REL. MAY BE OBTAINED BY MODIFYING A WARD LEONARD K42220 RELAY. THE MODIFICATION CONSISTS OF DISCARDING THE METAL HOUSING AND MOUNTING THE RELAY ON A BRACKET PER FIG. 4, THE BRACKET TO BE PROVIDED LOCALLY.
 3. THE BACK OF THE ELECTRICAL SERVICE UNIT SHALL BE DRILLED PER FIG. 3 FOR MOUNTING THE RELAY BRACKET.