




ASSEMBLY FOR ATTENDED TLX SERVICE WITH TTY SUB SET IN METAL CABINET
FIG. 1



ASSEMBLY FOR ATTENDED TLX SERVICE TTY SUB SET WITHOUT METAL CABINET
FIG. 2



TTY STATION ASSEMBLY 28B TTY CABINET ATTENDED TLX STATIONS 128C2, 128C3, OR 130BI TTY SUB SET WITH OR WITHOUT METAL CABINET