


ASSEMBLY FOR ATTENDED TLX SERVICE
 WITH TTY SUB SET IN METAL CABINET
FIG. 1



SECT. A-A

FR DISC
 09 AUX.
 JACK
 PANEL
 BOARD
 IN
 US
 BE
 128C2

SERVICE
 CABINET

P-30B514 MTG PLT ASSEM
 FURNISHED WITH ED-71172-01
 GROUP 3

P-41D318 RETAINING CLIP
 FURNISHED WITH ED-71172-01
 GROUP 3

TOP OF 128C2 OR 128C3
 TTY SUB SET

TOP OF 130BI TTY SUB SET

128C2, 128C3 OR 130BI
 TTY SUB SET WITHOUT
 METAL CABINET.


P-255706 RETAINING CLIP
 FURNISHED WITH ED-71172-01,
 GROUPS 1 OR 2


BOTTOM MTG PLT DRILLING

A


B

C





ASSEMBLY FOR ATTENDED TLX SERVICE
TTY SUB SET WITHOUT METAL CABINET
FIG. 2



SECT. A-A

P MTG PLT DRILLING
1A3 SUB SET WITH MFR DISC
A BACKBOARD
OR
17A3 SUB SET WITH
4A BACKBOARD
OR
4DG SUBSET
153017 SPEEDNUT
FINISHED WITH TPI52909
AUX. APPARATUS MOUNTING RACK

152909 AUX. APPARATUS
MOUNTING RACK (MUST BE
ORDERED SEPARATELY)

-5663 L7 RECT FOR
128C2 OR 128C3 TTY SUB SET
OR
-5663 L6 RECT FOR
130BI TTY SUB SET


P-30B518
MOUNTING SHELF ASSEM
FINISHED WITH
ED-71172-01,
G1 OR 2
153017 SPEEDNUT
FINISHED WITH TPI52909
AUX. APPARATUS MOUNTING
RACK

28B TTY CABINET

DETAILS OF TABLE
SCREWS

ASSEMBLY FOR ATTENDED TLX SERVICE
TTY SUB SET WITHOUT METAL CABINET

FIG. 2



MOUNTING DETAILS FOR TOP OF
128 TYPE TTY SUB SET
FURNISHED WITH ED-71172-01,G2
SECT. B-B

MOUNTING DETAILS FOR TOP OF
130BI TYPE TTY SUB SET
FURNISHED WITH ED-71172-01,G1
SECT. C-C

TTY STATION ASSEMBLY
28B TTY CABINET
ATTENDED TLX STATIONS
128C2, 128C3, OR 130BI TTY SUB SET
WITH OR WITHOUT METAL CABINET