



WIRING NOTES

1. USE "X" WIRING AT CUSTOMER'S OFFICE, AND "Y" WIRING AT CENTRAL OFFICE
2. WIRING NOT OTHERWISE SPECIFIED TO BE 22C
3. "PT" LEADS PART OF APPARATUS
4. REMOVE TERM. ON RED LEAD AND SOLDER TO KEY TERM.
5. SCHEMATIC SHOWN ON 20882-SD-129, ISSUE 2. EQUIPMENT SHOWN ON 20882-ED-105, ISSUE 2.

SWITCHING ARRANGEMENT

WIRING FOR
PORTABLE TESTING CIRCUIT
FOR 80 TYPE
RECEIVING SELECTOR