



ISS. NO.	DATE	C. D.	ISSUE	APPROVED	REMARKS	
					BY	DATE
1	4-4-29	BWK	5.P.S.			
2A	5-14-29	BWK	5.P.S.			
3A	6-20-29	BWK	5.P.S.			
4D	7-14-29	BWK	5.P.S.			
5D	11-15-29	BWK	5.P.S.			
6A	2-5-30	BWK	5.P.S.			
7-D	3-11-30	BWK	5.P.S.			
8-D	6-17-30	BWK	5.P.S.			

OPERATE IS CLEARLY REPEATING TELEGRAPH SIGNALS AT THE MAXIMUM SPEED OF HAND SENDING OR AT THE RATE OF 20 DOTS PER SECOND.

TEST NOTES:
 1. ALL KEYS IN THE POSITION SHALL BE NORMAL.
 2. THE (L) PLUG ASSOCIATED WITH TEST SET NO. 1 SHALL BE INSERTED IN THE (T) AND (R) JACK OF THE RELAY TEST BOX.
 3. THE (L) PLUG ASSOCIATED WITH TEST SET NO. 2 SHALL BE INSERTED IN THE JACK OF THE RELAY TEST BOX.



REPLACING ES-60363-01 AND I54-A-21

SD-62723-01

TOLL SYSTEMS
TELEGRAPH TEST BOARD NO. 9
 TELEGRAPH TEST CIRCUIT

A. T. & T. CO.
 STANDARD

AMERICAN TELEPHONE & TELEGRAPH CO.
 DEPT. OF DEVELOPMENT & RESEARCH
 BELL TELEPHONE LABORATORIES, INC.

SD-62723-01