



BUILDING NETWORKS FOR PEOPLE

D-Link Corporation confidential

## DIR-130 Firmware Release Notes

**Firmware: FW v1.23**

**Hardware: Rev.A1**

**Date: 2010/07/21**

### Problems Resolved:

1. Fix UPnP to cause WAN Setting be changed issue.
2. Change rate range unit from Kbytes to Kbits (Bandwidth Control feature).

### Enhancements:

1. Certificates be verified when to add IPSec/ SSL VPN rules.
2. Support full tunnel by IPSec (remote subnet accept IP address 0.0.0.0).
3. Pre-share key of IPSec accept particular character “!@#\$%^&\*()”.

### Known Issues:

None

----- END -----

**Firmware: FW v1.22**

**Hardware: Rev.A1**

**Date: 2009/08/24**

### Problems Resolved:

1. Fix DHCP reservation issue.
2. Fix PPTP and Russia Dual Access mode cannot auto reconnect issue.
3. Fix Bandwidth setting upstream or downstream to affect each other.

### Enhancements:

1. Support Graphical Authentication feature.
2. SSL Remote Management feature support IP address and port configuration.
3. SSL VPN support IP address configuration.
4. VPN wizard support.

### Known Issues:

None

D-Link Corporation confidential

---