



Firmware Version: V1.01b11
Prom Code Version:
Published Date: 2012/08/13

Content:

Upgrading Instructions: 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2011/6/28	DNS-1100-04	A1
V1.01b01	2011/10/26	DNS-1100-04	A1
V1.01b08 together with following software <ul style="list-style-type: none"> - D-View module 1.01R03-F1.01B07 - EZsearch 1.0.0.8 32bit/64bit - MIB v1.01 - Language pack v1.01 - Mac Storage Utility 1.0.0.12 	2011/12/29	DNS-1100-04	A1
V1.01b11	2012/08/13	DNS-1100-04	A1

Upgrading Instructions:

After firmware upgrade process complete, please power off then remove power code for 5 seconds. Re-plug power code and power on.

New Features:

Fireware Version	New Features
V1.00	Initial Release
V1.01b01	Bug fixed firmware
V1.01b08	<ul style="list-style-type: none"> • Resource Monitor • Multi-LUNs per Target • Supports LUN Mapping & LUN Masking • Supports MPIO • Supports MC/S • Supports Windows Server 2008 Hyper-V • Network access by service • AFP support • Syslog server • Network UPS • ISO mount • WebDAV • Amazon S3
V1.01b11	<ul style="list-style-type: none"> • Supports new FAN control mechanism • Changes FAN auto mode from (off-low-high) to (low-high) • MCU 0.00B12 to turn on FAN with high speed at booting stage

Problems Fixed:

Firmware Version	Problems Fixed
V1.00	N/A

V1.01b01	<ol style="list-style-type: none"> Fixed DUSA report issue/request <ul style="list-style-type: none"> - my favorite non consistent issue - re-login after changed admin password - show format percentage in Virtual Volume page - USB port description issue (from rear of view) - show percentage/speed in Local Backup folder mode - remove USB disk mount sync option - SSH login authorization, need to input password when ssh login. - Modify disconnecting power cord string when firmware MUC upgrade. Release Language package for Firmware v1.01
V1.01b08	<ol style="list-style-type: none"> Fixed "Can not connection when user used hostname in AD mode". Fix "empty domain user when there are very many users in AD server" issue. Fixed "\\ip\public issue(We do not support PnP-X driver now).
V1.01b11	<ol style="list-style-type: none"> Fixed "FAN control always on high mode to stop" Fixed "OLED doesn't show FAN failure if abnormal"

Known Issues:

Firmware Version	Known Issues
V1.00	N/A
V1.01	N/A

Related Documentation:

N/A