




2001-2006 Mini Cooper MAP Sensor Replacement

This video guide will teach you how to replace a MAP sensor in a 2001-2006 Mini Cooper. The instruction ends at 11:41 and continues on to the thermostat.

Written By: Sydtracked



This document was generated on 2019-11-05 06:25:55 PM (MST).

 **TOOLS:**

- 10mm Wrench (1)
- Flathead 3/32" or 2.5 mm Screwdriver (1)
- 1/4" Ratchet Extension (1)
- 3mm Hex Key (or Bit) (1)
- 10mm Socket (1)
- Socket Wrench (1)

 **PARTS:**

- MAP Sensor (1)

To reassemble your device, follow these instructions in reverse order.