



Asus Eee PC 1000HA Screen Replacement

This guide will show you how to replace the screen.

Written By: Ashlee Stickle



INTRODUCTION

In this guide we will provide you with the necessary information to replace the screen on an Asus Eee PC 1000HA.

TOOLS:

- [Phillips #00 Screwdriver](#) (1)
- [Metal Spudger](#) (1)
- [Magnetic Project Mat](#) (1)
- [Tweezers](#) (1)

Step 1 — Screen



- Remove the battery before working on your device. See this [LINK](#) for a step-by-step guide.
- Use the metal tweezers to remove all of the rubber pads from the face of the lap top.
- Removing the rubber pads will reveal 6 screws.

Step 2



- Use a #00 Phillips Head screw driver to remove the 4.8mm screws.
- There will be 6 screws total.

Step 3



- Use the metal spudger to pry off the outside frame of the screen.

Step 4



- Use the #00 Phillips Head screw driver to remove the 5.44mm screws.
- There are 6 screws total.

Step 5



- Use the metal spudger to gently remove the screen from the laptop.

Step 6



- Gently pull the tab that is connecting the laptop to the screen, to fully disconnect the screen from the laptop.

To reassemble your device, follow these instructions in reverse order.