



Fix Receiver Internal Error / Error 4000 / No Model Info

Full solution on how to fix the Internal Error/Error 4000 and No Model Info messages on various Yamaha Receivers.

Written By: Nick Myers



INTRODUCTION

Full solution on how to fix the Internal Error/Error 4000 and No Model Info messages on various Yamaha Receivers. This works with Yamaha RX-V673 and several other models.

Link to the current Yamaha firmware: <https://europe.yamaha.com/en/support/upd...>

To reassemble your device, follow these instructions in reverse order.