




# HP 7 1800 Audio Jack Replacement

This guide will help you replace the audio jack in your HP 7 1800.

Written By: Trevor Shumate





## INTRODUCTION

You will be disassembling the HP 7 1800 and using a soldering iron to replace the audio jack.

### TOOLS:


- Spudger (1)
- Portable Soldering Iron (1)
- Tweezers (1)

## Step 1 — Remove the back panel




- Use a Spudger to open the back panel. Be careful not to break the tabs.

## Step 2 — Desoldering the audio jack



- Desolder the top lead for the six solder points.

## Step 3 — Removing the audio jack



- Once the solder is removed, gently pull the audio jack away from the motherboard with tweezers.

To reassemble your device, follow these instructions in reverse order.