




HP Pavilion x360 15t-br000 Keyboard Panel Replacement

Use this guide to replace the keyboard panel in your HP Pavilion x360 15t-br000.

Written By: Justin Ogihara



INTRODUCTION

Pre-requisite only guide.

TOOLS:

- **Phillips #0 Screwdriver** (1)
- **Metal Spudger** (1)

Step 1 — Keyboard Panel



- Remove the covers to access the screws attached to the back cover of the device.
- Remove six 3mm screws using the Phillips #0 screwdriver.

Step 2



- Use a metal spudger to loose the four corners of the keyboard panel. The corner is circled red shown in the first image.
- Disconnect the keyboard panel cables under the upper case.
- Remove the keyboard panel from the device.

To reassemble your device, follow these instructions in reverse order.