




# HP x2 10-p010wm Battery Replacement

This guide will show you how to open the top and bottom of HP x2 10-p010wm to access its battery.

Written By: Vinh Phan



## INTRODUCTION

Model Number : HP x2 10-p010wm


If you are having troubles charging your HP x2 10-p010wm and your device failed the battery diagnose test from HP, it is most likely that you need to a battery replacement.

This guide will show you how to take apart the screen in order to access to the battery. But we recommend you to check our [troubleshooting page](#) first.

### **TOOLS:**


- [Phillips #0 Screwdriver](#) (1)
- [Metal Spudger](#) (1)

## Step 1 — Battery




- Pull the screen away from the keyboard.

## Step 2



- Insert a spudger into the space between the screen and computer and gently pry the two pieces apart. Continue this around the whole screen.


## Step 3



- Slowly disconnect the thin wire attaching the screen to the rest of the computer by holding one end and sliding it down.


 Do not pull up too hard; slowly slide it towards the screen.

## Step 4



- Remove the eight 4mm Phillips #00 screws from the metal plate.

## Step 5




- Slowly peel up any tape securing the wire to the metal cover.
- Remove the metal cover to access the battery.

## Step 6



- Remove the 4mm screw on the side.

## Step 7



- Remove the black tape.
- Pull the battery connector towards the battery to disconnect it from its socket.

## Step 8



- Remove the battery.

To reassemble your device, follow these instructions in reverse order.