



Hisense Sero 8 Charging Port Replacement

This guide demonstrates how to replace the charging port in the Hisense Sero 8.

Written By: Keanu



INTRODUCTION

After extended use, the charging port may be worn down. If the device will not power on after charging, the charging port may be defective.

TOOLS:

- [Phillips #00 Screwdriver](#) (1)
- [Spudger](#) (1)
- [iFixit Opening Tools](#) (1)
- [Tweezers](#) (1)

Step 1 — Charging Port





- Remove the back cover of the device using a combination of both plastic opening tools.
- Use your plastic opening tool pry open a corner of the device, then continue down the side of the device with the tool to completely open the device.

Step 2



- Remove seven of the 4.43mm screws using the Philips #00 screwdriver.
- *(i)* It is not necessary to remove the bottom two 4.43mm screws that keep the speakers in place.

Step 3



- Gently lift the motherboard up to extract the charging port out with the tweezers.

 Be cautious not to disconnect any wires or ribbon cables.

To reassemble your device, follow these instructions in reverse order.