



How To Fix GIGABYTE GV-R785OC-2GD Radeon HD 7850 Noisy Fan

Most people who buy these cards experience an annoying buzzing and vibration sound from these cards. The fix is simple!

Written By: Matthew Johnson



This document was generated on 2019-09-22 08:53:22 AM (MST).

 **TOOLS:**

- Phillips #2 Screwdriver (1)

 **PARTS:**

- Electrical Tape in 6 Assorted Colors (1)

Step 1 — How To Fix GIGABYTE GV-R785OC-2GD Radeon HD 7850 Noisy Fan



- remove the three Phillips screws under the fan closest to the video ports of the card

Step 2



- Lift the fan out(will be attached to a small cord but gets out of the way well) and shim a small cushion under the center circle, between the aluminum cooling fins and the plastic. I used electric tape, rolling it, sticky side in, to form about a 6 layer small square of tape. It shimmed in nicely.

Step 3



- Reassemble and re-install the card into your computer. It should stop the vibration.

To reassemble your device, follow these instructions in reverse order.