



Insignia NS-CSPGASP firmware update

This device may not download the latest firmware when it is initially configured

Written By: Eric Gosh

Press the microphone button for 12 seconds to factory reset.

Delete the device from Google home.

Add it to Google home.

The device can take more than 20 minutes to download the update. Disturbing it or the internet during this process could result in stuck on LOAD.