




Keenovo Bed Heater Installation

This guide overviews the installation of a Keenovo Bed Heater onto a Creality CR-10 S 500.




Written By: Tiny Machines 3D



 **TOOLS:**


- 2mm Hex Key (1)
- 2.5 mm Hex Key (1)
- Flush Wire Cutters (1)
- Squeegee (1)
- Isopropyl Alcohol (1)
- Paper Towels (1)
- High Temp (red) RTV Silicone (optional) (1)

Step 1 — Disassembly 1a.




- Insert wisdom here.

Step 2 — Disassembly 1b.



- Insert wisdom here.

Step 3 — Disassembly 1c.




- Insert wisdom here.

Step 4 — Disassembly 1d.



- Insert wisdom here.

Step 5 — Assembly 1a.




- Insert wisdom here.

Step 6 — Assembly 1b.




- Insert wisdom here.

Step 7 — Assembly 1c.




- Insert wisdom here.

Step 8 — Assembly 1d.



- Insert wisdom here.

Step 9



- Insert wisdom here.