



LG Phoenix 2 Headphone Jack Replacement

Replace your headphone jack on the LG Phoenix 2 if the sound quality is low or nonexistent.

Written By: Sarah Popp



INTRODUCTION

If you need to install a new headphone jack on your LG Phoenix 2, use this guide to disassemble and replace the damaged part. For this guide you will need a plastic opening tool and a Phillips #000 screwdriver. These steps will be straightforward and easy to follow, but the pieces should be handled with care, so as to not damage or misplace any needed components.

TOOLS:

- [iFixit Opening Tools](#) (1)
- [Phillips #0 Screwdriver](#) (1)

Step 1 — Headphone Jack



- Insert a fingernail into the notch on the bottom right corner of the phone.
- Pop off the back cover off of your device.

Step 2



- Insert a fingernail in the notch under the battery.
- Remove the battery.

Step 3



- Insert the opening tool under the bottom cover.
- Pop the bottom cover off.

Step 4



- Remove eight 3mm screws using a Phillips #0 screwdriver.

Step 5



- Insert the opening tool in between the phone screen and the silver trim.
- Pop off the trim.

Step 6



- Insert a screwdriver into the headphone jack.
- Pop out the headphone jack.

To reassemble your device, follow these instructions in reverse order.