



Ninja Coffee Bar® Single-Serve System Drip Stop Toggle and Brew Basket Replacement

If the drip stop is jammed/broken, or the brew basket is malfunctioning, follow this guide to replace or fix it.

Written By: Naser Aldousari



This document was generated on 2019-09-28 06:41:36 AM (MST).

INTRODUCTION

This guide will teach you how to get to the point where you can replace either the drip stop toggle and/or the brew basket. In a lot of coffee machines after heavy use the brew based can start to leak, and these fixes are very similar, so that is why we did both of these fixes together. Warning: be very careful when unscrewing the brew basket because there is a small spring that releases the drip stop toggle that needs to stay in place. Also you will need a longer skinnier Phillips head screwdriver than the one in the iFixit tool kit to complete this repair.

TOOLS:


- **Tweezers (1)**

Step 1 — Drip Stop Toggle and Brew Basket



- Slide brew baskets to open position

Step 2



- Unscrew three 6mm screws with Phillips head screw driver (need a thinner screwdriver than the one in the iFixit tool kit)

Step 3



- Using needle nose tweezers, push the bottom of the pin up from behind the brew basket
- Using needle nose tweezers, pull out the pin

Step 4



- Remove brew basket from swinging basket holder

Step 5



- Unscrew one 6mm screw from drip stop toggle
- Remove drip stop toggle

To reassemble your device, follow these instructions in reverse order.