



Repairing Logitech H800 Wireless Headset Fix the rattling on the right ear piece.

In this guide you will silence the rattling of the media controls on the right earpiece.

Written By: SYN1ST3R



INTRODUCTION

Owners of this headset are most likely aware of the rattling it makes when you move around. This is one of the biggest complaints of this headset and it can be easily fixed.

TOOLS:

- [Phillips #000 Screwdriver](#) (1)
- [T5 Torx Screwdriver](#) (1)
- [Tweezers](#) (1)

PARTS:


- [Small piece of foam](#) (1)

Step 1 — Repairing Logitech H800 Wireless Headset Fix the rattling on the right ear piece.



- Remove the foam speaker cover. Locate (4) T5 Torx screws and remove.

Step 2



- Remove (3) Phillips #000 screws.
- Remove circuit board

Step 3



- Optional, remove media buttons section by removing (3) Phillips #000 screws.
- Cut a circular piece of foam and stuff it under the center section.
- **You are now finished! Just reassemble**

To reassemble your device, follow these instructions in reverse order.