




Smartab STJR700 Screen/Digitizer Replacement

This replacement will improve the touch screen performance if your screen was cracked.

Written By: Tianna Edwards



 **TOOLS:**

- Flathead 3/32" or 2.5 mm Screwdriver (1)
- iFixit Opening Tools (1)

 **PARTS:**

- Screen Replacement (1)

Step 1 — Screen/Digitizer



- Use the screwdriver and the J10 tip to unscrew the back of the device. There are four screws; one on each corner.

Step 2



- Separate the back of the device from the front panel exposing the digitizer along with the other electronic components.

Step 3



- Remove the circuit board from the front panel and screen, leaving the digitizer and circuit board intact.
- Separate the existing, damaged glass from the front panel.

To reassemble your device, follow these instructions in reverse order.