



Sony Ericsson Xperia X10 Audio Jack Replacement

User will be able to dissemble the phone, locate and replace the audio jack

Written By: Bryan



 **TOOLS:**

- [Flathead Screwdriver](#) (1)
- [T6 Torx Screwdriver](#) (1)

Step 1 — Audio Jack



- The audio jack is located on the top side of the phone, in the center. To access the audio jack disassemble is necessary.

Step 2



- Start by having the screen of the phone facing downwards and remove the battery. Remove eight 5mm screws located as shown with a T-6 bit.

Step 3




- Using a case opener, start on the bottom right side of the phone and undo clips located at the interior sides. Repeat this step for the left side.

Step 4




- Once the clips are undone the back casing should dislocate and reveal the internal components of the phone. Audio jack location is identified on the image.

Step 5



- The audio jack can only be accessed if the internal casing is removed. To remove this, apply pressure on the left side of internal casing and using a flat head screw driver unlatch both clips on the right side of casing.

Step 6



- Audio Jack is located and easily removed. New component can be inserted.

To reassemble your device, follow these instructions in reverse order.