



Texas Instruments TI-5130 Printer Unit Replacement

If your calculator has stopped printing and/or will not feed paper you may need to replace the printing unit, shown here.

Written By: Shannon Perkins



INTRODUCTION

Follow this guide to remove and replace the printing unit in the TI-5130 electronic calculator.



TOOLS:

- [Phillips #1 Screwdriver](#) (1)



PARTS:

- [TI-5130 Printer Unit](#) (1)

Step 1 — Printer Unit




- Flip the calculator over and remove the 4 main 10mm screws with a PH1 screwdriver.

Step 2



- Flip the calculator back over and remove the top cover.

Step 3




- Disconnect the printing unit from the motherboard by pulling up on the connector – located in the bottom left of the motherboard.

Step 4



- Remove the ink cartridge by pushing the tab back then lifting it out to gain access to the screw that holds the printer in place.

Step 5



- Using a PH1 screwdriver remove the 10mm screw that holds down the printer unit.
- Remove the printer unit by lifting it up.

To reassemble your device, follow these instructions in reverse order.