




# Turtle Beach Elite 800 Charging Pins on Headset Replacement

This guide will show how to replace the charging contacts inside the right ear of the headset.

Written By: Johnny Lofton



## INTRODUCTION

This is a guide on how to replace the contact pins inside of the headset.

### TOOLS:


- [Phillips #00 Screwdriver](#) (1)
- [Phillips #0 Screwdriver](#) (1)

## Step 1 — Ear Cushion




- Remove previous ear cushion by rotating the clockwise and pulling it off.
- When reassembling, be sure to line up the locking plates.

## Step 2 — Charging Contact Pins on Headset



- Use the Phillips #0 screw bit to remove the four screws (9.47 mm long) that have been revealed from removing the ear cup. Carefully take off the blue casing to reveal the audio board.

## Step 3



- Use the Phillips #00 screw bit to remove the two screws (7.92 mm long) that are holding the contact pins in place.
- Then, simply push the pins from the board.

To reassemble your device, follow these instructions in reverse order.