




Zoom H1 Handy Recorder Battery Terminal Replacement

This guide will show you how to remove and replace faulty battery terminals on your device.

Written By: Alex



This document was generated on 2019-09-18 09:24:58 AM (MST).

INTRODUCTION

Outline what you are going to teach someone how to do.

TOOLS:

- [Soldering Iron](#) (1)
- [Phillips #00 Screwdriver](#) (1)
- [iFixit Opening Tools](#) (1)

Step 1 — Battery Terminal



- Place the device so the display is down.

Step 2



- Remove the battery cover, pressing down on the tabs and sliding.

Step 3




- Unscrew the two (2) #00, 10 mm screws located below the mic on the back cover

Step 4




- Carefully pry up the top end of the back cover using one finger

Step 5




- Remove the back plate by using a plastic removal tool to pry the back cover up around the edges.

Step 6





- De-solder at terminal point one.

Step 7




- De-solder at the second terminal point.

Step 8




- Remove the faulty terminals

Step 9



- Place new lead in at point one and re-solder at the point.

Step 10



- Place second lead at point 2 and re-solder.

To Re-construct device, perform these steps in reverse order.