




iMac Intel 21.5" Retina 4K Display Fan Replacement

Prerequisite for removing fan after the hard drive brackets.

Written By: Evan Noronha





INTRODUCTION

Prerequisite only.

TOOLS:

- T10 Torx Screwdriver (1)

Step 1 — Fan





- Gently pull the fan cable connector straight out of its socket on the logic board.

Step 2



- Remove the three 10 mm T10 Torx screws securing the fan to the rear enclosure.
(i) The uppermost screw has a rubber standoff adhered to its head to support the display—leave this in place.

Step 3



- Remove the fan from the iMac.

To reassemble your device, follow these instructions in reverse order.