




iPad 3 4G Antenna Connectors Replacement

Internal Prerequisite

Written By: Brett Hartt



Li-ion Polymer Battery
Model No.: A1389
3.7V 43.0Whr 11560mAh
APN: G16-0591
VPN: DAK121190-W020H01LH
Assembled in China

WARNING
Potential for fire or
burning. Do not
disassemble, puncture,
crush, heat, or burn.

美国苹果公司 型号:A1389
中国制造 原电池
产品标准: GB4943-2001
GB/T18287-2000
充电限制电压 4.2V


INTRODUCTION

Internal Prerequisite

TOOLS:

- [Phillips #00 Screwdriver](#) (1)

Step 1 — Antenna Connectors



- Remove the seven screws securing the logic board to the rear aluminum panel.
 - Six 2.1mm Phillips #00
 - One 2.5mm Phillips #00

Step 2



- Flip the logic board over, minding any cables that may get caught.
- Using the tip of a spudger, remove the three antenna connectors from their sockets on the logic board.

To reassemble your device, follow these instructions in reverse order.