



1999-2004 Honda Odyssey EGR Port Cleaning

A video tutorial on how to clean the EGR port on a 1999-2004 Honda Odyssey. Also helps if you are reading a code of P0401.

Written By: eCuration



INTRODUCTION

The EGR value on the 1999-2004 Honda Odyssey is notorious for becoming clogged. If you are getting a P0401 code and or odd running issues then follow this guide to clean the valve.

TOOLS:

- 3/8" Drive Ratchet (1)
- 10" Ratchet Extension (1)
- 10mm Socket (1)
- 10mm Wrench (1)
- Pick Tool (1)
- Throttle Body and Air-Intake Cleaner (Carb) (1)
- 12mm Socket (1)

PARTS:

- Intake Gasket (1)

To reassemble your device, follow these instructions in reverse order.