Logitech K830 Repair USB connector Replacement

Written By: mathieubernou

This document was generated on 2019-09-18 02:15:52 PM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 1 of 8

🔧 TOOLS:

- Essential Electronics Toolkit (1)

　　　　　　　　　　　www.iFixit.com

Step 1 — Repair USB connector

- Turn the keyboard over so the back is facing up.

Step 2

- Remove the 4 rubbers hiding 4 screws

This document was generated on 2019-09-18 02:15:52 PM (MST).

© iFixit — CC BY-NC-SA

www.iFixit.com

Page 3 of 8

Step 3

- Unscrew the 8 visible screws

Step 4

- Unclip the two plastic side of the keyboard

⚠️ Careful the maximum opening distance range is limited by an internal connection. Open gently.

Step 5

- Unplug the connection avoid the separation of the two plastic parts.

Step 6

- Unplug the battery connector from the base side

- You can now separate the two part of the keyboard

Step 7

- Repair the soldering of the micro USB connector

Step 8

- Plug the battery connector

This document was generated on 2019-09-18 02:15:52 PM (MST).

Step 9

- Plug the connection from the upper part of the keyboard

Step 10

- Reassemble both keyboard parts

- Clip them together

Step 11

- Screw in the 8 screws

Step 12

- Stick the 4 rubbers at their respective positions

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2019-09-18 02:15:52 PM (MST).