



Rapoo E6700 Bluetooth Touch Keyboard Teardown

This 'guide' shows that it is NOT possible to repair a damaged USB connector on this device.

Written By: Thomas Widmaier




INTRODUCTION


Here I'm showing a repairability index of -1 aka bad design.

This Keyboard has been glued together not only with double sided tape but also with superglue making it impossible to repair. All I wanted was to replace the USB connector!

Step 1 — Rapoo E6700 Bluetooth Touch Keyboard Teardown



Step 3




- Well for those who try to get the keyboard off, someone has developed superglue.
- Yes you heard it, not just sticky double sided tape, also superglue applied in the marked areas.

Step 4



- Here's the keyboard after 1 hour trying to separate the parts.
- And another view of the superglue residuals on the keyboard side.

Step 5



- This is the '**repaired**' keyboard
- and the only reason to repair: the broken off (badly soldered) USB connector.
- What a waste of materials

To reassemble your device, buy a new one