Repairing Nokia Lumia 520 Power Button

A trick for repair the power button of the Lumia 520.

Written By: keroro90

TOOLS:

- Pro Tech Toolkit (1)

This document was generated on 2019-09-19 03:35:30 PM (MST).

Step 1 — Repairing Nokia Lumia 520 Power Button

- Remove the back cover from the phone.

Step 2

- Take a bus ticket or anything else that has a thickness of 0.5-0.6 mm.

- Cut the ticket to form a triangle.

- Insert the triangle in the gap between the button and the chassis.

www.iFixit.com

Step 3

- Cut the part of the ticket that is out of the chassis.

- Now with a paper clip tests if it works.

- If it works remount the back cover. If i doesn't work probably the problem is the button and not the contact and you need to replace it.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2019-09-19 03:35:30 PM (MST).